

**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 01/07/08

FACILITY NAME: Village of Roaming Shores

OHIO NPDES PERMIT NO: 3PB00068*FD

PERIOD COVERED BY REPORT: 2007

CONTACT PERSON

NAME: Barry French

TITLE: Wastewater Superintendent

MAILING ADDRESS:

2500 Hayford Road PO Box 237 Roaming Shores OH 44084


TELEPHONE: 440-576-3724

EMAIL: bafrench@co.ashtabula.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.



Signature of Official



Date

Wastewater Superintendent

Title

SSO Annual Report Table 3: Water In Basement Occurrences Ohio NPDES Permit No.: 3PB00068*FD

Sewershed ^A	WIB Occurrences ^B	Causes ^C
N/A		
Total Occurrences	0	

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.

B. Enter the total number of water in basement occurrences reported for the sewershed.

C. Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.

Enter narrative
analysis of WIB
patterns by location,
frequency and cause.

A large, empty rectangular box with a black border, intended for the user to enter a narrative analysis of Water In Basement (WIB) patterns. The box is currently blank.